



GKN Aerospace  
Chem-tronics Inc.

# Rolls Royce RB211-535E4

## ANNULUS FILLER



### Reference

Engine Manual 72-31-11

### Typical Part Numbers

UL16208, UL35848, UL35853, UL38852, UL38855

### General Information

22 Fillers per Engine

Aircraft Type: B757

## Available Repair Scope

### Basic Overhaul:

Engine Manual Inspections

FRS 3002	Repair 1 - Replace Wire Thread Inserts
FRS 3253	Repair 1 - Blend Minor Damage
FRS 5135	Repair 1 - Replace Air Sealing Strips and Buffer Pads
FRS 1520	Repair 2 - Apply White Epoxy Paint
FRS 1521	Repair 3 - Reapply Dry Film Lubricant
FRS 5742	Repair 32 - Anodizing Coating

### Service Bulletins:

SB 72-C545 Eddy Current Inspection



1150 West Bradley, El Cajon, CA 92020

www.chem-tronics.com (619) 258-5229

*Proprietary Information - Revised 03-15-2006*