



GKN Aerospace
Chem-tronics Inc.

Rolls Royce Trent 800

ANNULUS FILLER



Reference

Engine Manual 72-31-11

Typical Part Numbers

FK21221

General Information

26 Fillers per Engine

Aircraft Type: B777

Available Repair Scope

Basic Overhaul:

Engine Manual Inspections

FRS 3253 Blend Minor Damage

FRS A056 Repair 12 - Replace Air Sealing Strips and Buffer Pads

FRS A043 Repair 2 – Local Anodize as required and Apply Surface Protection, White Epoxy Paint

FRS A046 Repair 3 - Reapply Dry Film Lubricant



1150 West Bradley, El Cajon, CA 92020

www.chem-tronics.com (619) 258-5229

Proprietary Information - Revised 03-15-2006